

ReleaseOrder ID: DCSG01271877
Headline: Unified StorCLI Phase 24 - StorCLI release order 007.2307.0000.0000
Release Version: 007.2307.0000.0000
UCM Project: SAS35_StorCLI_7x
Sub UCM Project: SAS35_StorCLI_7_23_PH24
UCM Stream:
Release Type: GCA
State: Released
Release Baseline: Release-SAS35_StorCLI_7_23_PH24-007.2307.0000.0000-DCSG01271877-2022-07-22-15-07-14
Release Date: 2022-07-22 09:31:15.000000
Date Generated: Aug 08, 2022

Defects Fixed (1):

ID: DCSG01264998
Headline: Storcli needs a reboot message when activating
Description Of Change: Storcli needs a reboot message when activating
Issue Description: Storcli needs a reboot message when activating
Steps To Reproduce: Storcli needs a reboot message when activating

Release History

- [DCSG01267769 - Unified StorCLI Phase 24 - StorCLI release order 007.2306.0000.0000](#)
- [DCSG01257679 - Unified StorCLI Phase 24 - StorCLI release order 007.2305.0000.0000](#)
- [DCSG01232384 - Unified StorCLI Phase 24 - StorCLI release 007.2302.0000.0000](#)
- [DCSG01211844 - Unified StorCLI Phase 24 - StorCLI release order v007.2301.0000.0000](#)
- [DCSG01194460 - Unified StorCLI Phase 24 - StorCLI release 007.2300.0000.0000](#)

ReleaseOrder ID: [DCSG01267769](#) [Open In CQWeb](#)
Headline: Unified StorCLI Phase 24 - StorCLI release order 007.2306.0000.0000
Release Version: 007.2306.0000.0000
UCM Project: SAS35_StorCLI_7x
Sub UCM Project: SAS35_StorCLI_7_23_PH24
UCM Stream:
Release Type: Beta
State: Released
Release Baseline: Release-SAS35_StorCLI_7_23_PH24-007.2306.0000.0000-DCSG01267769-2022-07-18-17-32-57
Release Date: 2022-07-18 11:15:00.000000
Date Generated: Aug 08, 2022

ReleaseOrder ID: [DCSG01257679](#) [Open In CQWeb](#)
Headline: Unified StorCLI Phase 24 - StorCLI release order 007.2305.0000.0000
Release Version: 007.2305.0000.0000
UCM Project: SAS35_StorCLI_7x
Sub UCM Project: SAS35_StorCLI_7_23_PH24
UCM Stream:
Release Type: Beta
State: Released
Release Baseline: Release-SAS35_StorCLI_7_23_PH24-007.2305.0000.0000-DCSG01257679-2022-07-04-12-59-36
Release Date: 2022-07-04 07:05:02.000000
Date Generated: Aug 08, 2022

Defects Fixed (2):

ID: DCSG01252449
Headline: There is no info message while downloading the "psoc" image.
Description Of Change: Added downloading image message for PSOC catalog file also.
Issue Description: Downloading message is displayed for all components except PSOC catalog file.
Steps To Reproduce: Download PSOC catalog file.

ID: DCSG01253543
Headline: Storcli does fails to turn on security with new option
Description Of Change: Storcli does fails to turn on security with new option
Issue Description: Storcli does fails to turn on security with new option
Steps To Reproduce: Storcli does fails to turn on security with new option

ReleaseOrder ID: [DCSG01232384](#) [Open In CQWeb](#)
Headline: Unified StorCLI Phase 24 - StorCLI release 007.2302.0000.0000
Release Version: 007.2302.0000.0000
UCM Project: SAS35_StorCLI_7x
Sub UCM Project: SAS35_StorCLI_7_23_PH24
UCM Stream:
Release Type: Beta
State: Released
Release Baseline: Release-SAS35_StorCLI_7_23_PH24-007.2302.0000.0000-DCSG01232384-2022-06-02-23-03-06
Release Date: 2022-06-03 17:25:02.000000
Date Generated: Aug 08, 2022

Defects Fixed (2):

ID: DCSG01214343
Headline: New PSOC related properties are not being displayed
Description Of Change: Added below PSOC properties to /c0 show all command.
1. PSOC FW Version
2. PSOC Part number
3. PSOC Support bits
Issue Description: Newly added PSOC properties are not being displayed.

1. PSOC FW Version
2. PSOC Part number
3. PSOC Support bits

Steps To Reproduce: Phase 24 - New PSOC related properties are not being displayed.

Below properties are not being displayed.

1. PSOC Part number.
2. PSOC support bit information.

ID: DCSG01225927

Headline: autoconfig lowlatency change option is not working

Description Of Change: Updated CLI to fetch the key value properly and allowing for value low and sending the request accordingly.

Issue Description: autoconfig lowlatency change option is not working

Steps To Reproduce: autoconfig lowlatency change option is not working

Enhancements Implemented (1):

ID: DCSG01219438

Headline: Allow CLI to run on perc branded cards

Description Of Change: Removed the check in the controller enumeration for storcli64 where we prevent perc controllers being discovered. Based on binary stamping, the customization is done in the cli and not based on controller OEM.

ReleaseOrder ID: [DCSG01211844](#) [Open In CQWeb](#)

Headline: *Unified StorCLI Phase 24 - StorCLI release order v007.2301.0000.0000*

Release Version: *007.2301.0000.0000*

UCM Project: *SAS35_StorCLI_7x*

Sub UCM Project: *SAS35_StorCLI_7_23_PH24*

UCM Stream:

Release Type: *Alpha*

State: *Released*

Release Baseline: *Release-SAS35_StorCLI_7_23_PH24-007.2301.0000.0000-DCSG01211844-2022-05-11-19-01-32*

Release Date: *2022-05-11 13:23:10.000000*

Date Generated: *Aug 08, 2022*

Enhancements Implemented (1):

ID: DCSG01203368

Headline: 95xx HBA controllers - Support for multiple PSOC images

Description Of Change: CLI will support PSOC catalog images for 95xx controllers. CLI will check the controller psoc part number against the part number advertised in the catalog file and if we find a match, we will send the corresponding PSOC image to download.

Also, CLI will display corresponding PSOC specific properties to the user.

ReleaseOrder ID: [DCSG01194460](#) [Open In CQWeb](#)

Headline: *Unified StorCLI Phase 24 - StorCLI release 007.2300.0000.0000*

Release Version: *007.2300.0000.0000*

UCM Project: *SAS35_StorCLI_7x*

Sub UCM Project: *SAS35_StorCLI_7_23_PH24*

UCM Stream:

Release Type: *Pre-Alpha-2*

State: *Released*

Release Baseline: *Release-SAS35_StorCLI_7_23_PH24-007.2300.0000.0000-DCSG01194460-2022-04-23-00-31-59*

Release Date: *2022-04-22 18:52:41.000000*

Date Generated: *Aug 08, 2022*

Defects Fixed (1):

ID: DCSG01187424

Headline: volume table is not listed in sorted order for "cx show all" command

Description Of Change: Updated the volume table for show all command to display in sorted order

Issue Description: volume table is not listed in sorted order for "cx show all" command

Steps To Reproduce: volume table is not listed in sorted order for "cx show all" command

Enhancements Implemented (2):

ID: DCSG01132479

Headline: SecureBoot: FW download operation fails with incorrect message

Description Of Change: Added a new SL error code. And displaying appropriate error message when the user tries to flash the FW binary which is not signed using the correct-key

ID: DCSG01191525

Headline: Displaying PackageVersion for Aero-IT Images

Description Of Change: Displaying PackageVersion for Aero-IT Images by referring the Applicationspecific field storcli64 show file=aero-it.rom